

# Technical Service Bulletin

**NUMBER:** 08-038-00

**GROUP:** Electrical

**DATE:** Dec. 8, 2000

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.*

**SUBJECT:**

Safety Systems – Vehicle Modifications/Repair

**MODELS:**

2001	(AB)	Ram Van/Wagon
2001	(AN)	Dakota
2001	(BR/BE)	Ram Pickup
2001	(DN)	Durango
2001	(JR)	Sebring Sedan/Stratus Sedan/Sebring Convertible
2001	(LH)	Concorde/Intrepid/LHS/300M
2001	(PL)	Neon
2001	(PR)	Prowler
2001	(PT)	PT Cruiser
2001	(RS)	Town & Country/Caravan/Voyager
2001	(RG)	Chrysler Voyager (International Markets)
2001	(SR)	Viper
2001	(ST)	Sebring Coupe/Stratus Coupe
2001	(TJ)	Wrangler
2001	(WJ)	Grand Cherokee
2001	(WG)	Grand Cherokee (International Markets)
2001	(XJ)	Cherokee

**DISCUSSION:**

Current DaimlerChrysler vehicles may contain any or all of the following safety systems: driver airbags, passenger airbags, side curtain airbags, side seat airbags, or seat belt pre-tensioners. All these systems contain multiple sophisticated sensitive electrical and mechanical components. The location and function of all safety system components must be determined before performing repairs; including accident, mechanical or electrical, or vehicle modifications such as adding an after-market sunroof.

**WARNING: ANY INADVERTENT SAFETY SYSTEM COMPONENT OR ASSOCIATED WIRING DAMAGE/MODIFICATION OR COMPONENT LOCATION CHANGE MAY DISABLE ANY OF THE SAFETY SYSTEMS.**

Refer to the appropriate vehicle Service Manual to determine location and function of all safety systems before servicing vehicle. All systems should be checked for functionality after the vehicle modifications/repairs are complete.

***POLICY:***

Information Only