

Technical Service Bulletin

NUMBER: 23-35-99 Rev. A

GROUP: Body

DATE: Oct. 1, 1999

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without written permission of DaimlerChrysler Corporation.

THIS BULLETIN SUPERSEDES TECHNICAL SERVICE BULLETIN 23-35-99 DATED SEPTEMBER 3, 1999, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS AND INCLUDE CHANGES IN SOME TIME ALLOWANCES.**

SUBJECT:

Child Seat Tether Anchors

NOTE: THIS BULLETIN DOES NOT APPLY TO DAIMLERCHRYSLER CANADA DEALERS.

MODELS:

1989 - 1995 (AA)	Spirit/Acclaim/LeBaron Sedan
1989 - 2000 (AB)	Ram Van/Wagon
1989 - 1993 (AC)	Dynasty/New Yorker/New Yorker Salon
1989 - 1994 (AG)	Daytona
1989 (AH)	Lancer/Lebaron GTS
1989 - 1993 (AJ)	LeBaron Coupe
1989 - 1990 (AK)	Aries/Reliant
1989 - 1990 (AL)	Horizon/Omni
1989 (AM)	Diplomat/Gran Fury/New Yorker Fifth Avenue
1989 - 2000 (AN)	Dakota
1989 - 1994 (AP)	Shadow/Sundance
1989 - 1995 (AS)	Town & Country/Caravan/Voyager
1990 - 1993 (AY)	Imperial/New Yorker Fifth Avenue
1988 - 1992 (BB)	Monaco/Premier
1990 - 1994 (BD)	Laser/Talon
1994 - 2000 (BR/BE)	Ram Truck
1989 - 1992 (B2)	Colt/Summit
1992 - 1995 (B3)	Colt Vista
1989 (B5)	Conquest
1989 - 1995 (B7)	Stealth (2000 GTX Dodge/Eagle, Canada)
1992 - 1995 (B8)	Colt Vista Wagon/Summit Wagon
1993 - 1994 (B9)	Colt/Summit
1998 - 2000 (DN)	Durango
1995 - 1999 (FJ)	Sebring/Avenger/Talon
1995 - 1999 (JA)	Cirrus/Stratus/Breeze
1993 - 1999 (LH)	Concorde/Intrepid/Vision/LHS/New Yorker/300M
1996 - 2000 (NS)	Town & Country/Caravan/Voyager
1995 - 2000 (PL)	Neon
1997 - 1999 (PR)	Prowler
1996 - 1999 (SR)	Viper/Viper GTS
1999 - 2000 (WJ)	Grand Cherokee
1989 - 2000 (XJ)	Cherokee/Wagoneer
1993 - 1998 (ZJ)	Grand Cherokee/Grand Wagoneer

NOTE: THIS BULLETIN IS PROVIDED TO IDENTIFY THE PARTS AND LABOR OPERATION NUMBERS NECESSARY TO INSTALL A CHILD SEAT TETHER ANCHOR. DAIMLERCHRYSLER WILL REIMBURSE YOU FOR THE ANCHORS AND LABOR TO INSTALL THEM. THIS IS BEING DONE IN THE INTEREST OF CUSTOMER SATISFACTION. REFER TO GLOBAL WARRANTY ADMINISTRATION BULLETIN #D-99-23 FOR COMPLETE REIMBURSEMENT INSTRUCTIONS.

DISCUSSION

User-ready child restraint tether strap anchors will be provided in passenger cars in the 2000 Model Year, and in light truck in the 2001 Model Year. Tether straps improve the performance of child restraints in collisions. Because of the publicity that has accompanied the "Fit for a Kid" Program, owners of earlier products are expected to approach dealers for the free provision and installation of the anchor hardware. DaimlerChrysler Corporation is offering child seat tether anchors for the selected vehicles listed above. Each tether anchor is packaged in a kit containing all necessary parts and a detailed instruction sheet.

PARTS REQUIRED:

BODY	MODEL	YEAR	CENTER	OUTBOARD
AA	LeBaron Sedan/Spirit/Acclaim	89-95	04519071AB	04519071AB
AB	Ram Wagon	89-00	04358469AB	04358469AB
AC	New Yorker/ Landau/Dynasty	89-93	04519073AB	04519072AB
AG	Daytona	89-90	NA	05003422AB
		91-94	NA	04519074AB
AH	Lancer/LeBaron GTS	89	04519076AB	05003422AB
AJ	LeBaron Coupe	89-93	04519077AB	04519077AB
AK	Aries/Reliant	89-90	04519077AB	04519077AB
AL	Horizon/Omni	89-90	04519081AB	04519080AB
AM	Diplomat/Gran Fury/N.Y.Fifth Avenue	89	04519077AB	04519077AB
AN	Dakota	88-99	05014765AA	05014765AA
	AN84: 4-Door	00	05016573AA	05016573AA
	AN31: Extended Cab	00	05016572AA	05016572AA
	AN61 : Standard Cab	00	05017683AA	05017683AA
AP	Shadow/Sundance	89-94	04519292AB	04519292AB
AS	Town & Country/Caravan/Voyager	89-95	05017529AA	05017529AA
AY	Imperial/New Yorker Fifth Avenue	90-93	04519071AB	04519071AB

BODY	MODEL	YEAR	CENTER	OUTBOARD
BB	Monaco/Premier	89-92	04519077AB	04519077AB
BD	Laser/Talon	90-94		
	Anchor		MB590094	MB590094
	Bolt		MF140225	MF140225
	Bracket Left		MB593349	MB593349
	Bracket Right		MB593350	MB593350
BR/BE	Ram Truck	94-00	05017032AA	05017032AA
B2	Colt/Summit	89-92		
	4-Door		MB597261	MB612814
	2-Door		MB865730	MB597261
B3	Vista	92-95	MB583400	MB583400
5	Chrysler Conquest	87-89	MB597261	MB597261
B7	2000GTX Dodge/Eagle - Canada Stealth	89-91	MB597261	MB597261
		92-95	MB597261	MB597261
B8	Colt Vista Wagon/Summit Wagon	92-95	MB583400	MB583400
B9	Colt/Summit	93-94		
	4-Door		MB865730	MB865730
	2-Door		MB597261	MB597261
DN	Durango	98-00	NA	
	Standard Seat			05012007AB
	60/40 Seat			05015403AA
FJ	Avenger/Sebring	95-99	MB597261	MB612814
FJ	Talon	95-97	MB583400	MB583400
JA	Breeze/Cirrus/Stratus	95-99	04519077AB	04519077AB
LH	Intrepid/Concorde/Vision New Yorker/LHS LHS/300M	93-99	04519077AB	04519077AB
		94-97	04519077AB	05017645AA
		99	04519077AB	04519077AB
NS	Town & Country/Caravan/Voyager	96-00	04864118AB	04864118AB
PL	Neon (Built prior to 9-1-99)	95-00	05017563AB	05017563AB
PR	Prowler	97-99	NA	05017570AA
SR	Viper	96-99	NA	04883004AB
WJ	Jeep Grand Cherokee Canada	99-00	NA	05016871AA Trim-Camel Or 05016873AA Trim Taupe

BODY	MODEL	YEAR	CENTER	OUTBOARD
WJ	Jeep Grand Cherokee US	99-00	NA	05016869AA Trim Camel Or 05016870AA Trim Taupe
XJ	Jeep Cherokee US Canada	89-99 00 00	NA	05003422AB 05017540AA 55315034AA
ZJ	Jeep Cherokee/Grand Wagoneer	93-98	04728952AB	NA

POLICY: Customer Satisfaction

<u>Labor Op. Number</u> <u>Allowance</u>	<u>Description</u>	<u>Vehicle App./Year</u>	
23-13-12-90	Anchor, Child Seat Tether – Install One	1989-95 (AA) 1989-94 (AG, AP) 1989 (AH, AM) 1989-93 (AJ) 1989-90 (AK, AL) 1988-92 (BB) **1994-2000 (BR, BE)	0.2
		1995-99 (JA) 1995-2000 (PL) 1996-1999 (SR)	0.2**
		1989-93 (AC) 1990-93 (AY) 1995-99 (FJ) 1993-99 (LH)	0.3
		1989-95 (AS) 1996-2000 (NS) 1989-2000 (XJ) 1993-98 (ZJ)	0.4
		1989-2000 (AB)	0.5
		1989-95 (B7)	0.5
		1990-94 (BD)	0.5
		1989-92 (B2)	0.5
		1992-95 (B3, B8)	0.5
		1989 (B5)	0.5
		1993-94 (B9)	0.5
		1999-2000 (PR)	0.5

23-13-12-91	Anchor, Child Seat Tether – Install Two	**1994-2000 (BE)	0.2**
		1989-2000 (DN)	0.2
		1989-95 (AA)	0.3
		1989-94 (AG, AP)	
		1989 (AH, AM)	
		1989-93 (AJ)	
		1989-90 (AK, AL)	
		1988-92 (BB)	
		1995-99 (JA)	
		1995-2000 (PL)	
		1999-2000 (WJ)	0.3
		1989-93 (AC)	0.4
		1990-93 (AY)	
		1993-99 (LH)	
		1989-95 (AS)	0.5
		1996-2000 (NS)	
		1989-2000 (XJ)	0.6
1989-2000 (AB)	0.7		
1989-2000 (AN)	1.0		
23-13-12-92	Anchor, Child Seat Tether – Install Three	1989-95 (AA)	0.4
		1989 (AH, AM)	
		1989-93 (AJ)	
		1989-90 (AK, AL)	
		1989-94 (AP)	
		1988-92 (BB)	
		1995-99 (JA)	
		1995-2000 (PL)	
		1989-93 (AC)	0.5
		1990-93 (AY)	
		1993-99 (LH)	
		1996-2000 (NS)	0.6
1989-2000 (AN)	1.2		

Failure Code: CG – Customer Satisfaction